

## FOCTT2 Firmware Update Tool for macOS v1.0.9

## Contents

General .....	2
Supported Hardware.....	2
Supported OS Compatibility .....	2
Tested OS Compatibility .....	2
Released Production Files.....	2
Product Upgrade .....	2
New Features.....	3
New Features added in version 1.0.9 .....	3
Resolved Issues .....	4
Issues resolved by version 1.0.9 .....	4
Outstanding Issues.....	5
New Issues .....	5
Existing Issues.....	5
Document History .....	6

Copyright © 2020 Panduit Corp. All rights reserved. No part of this book shall be reproduced, stored in a retrieval system, or transmitted by any means, electronic, mechanical, photocopying, recording or otherwise, without written permission from Panduit. No patent liability is assumed with respect to the use of the information contained herein.

Although every precaution has been taken in the preparation of this book, Panduit assumes no responsibility for errors or omissions. Neither is any liability assumed for damages resulting from the use of the information contained herein.

## General

V1.0.9 is a GENERAL RELEASE of the OCTT2 Firmware Update Tool.

## Supported Hardware

<i>Model</i>	<i>Required Firmware to support Release</i>	<i>Notes</i>
OCTT2	Boot loader v2.03 and newer Firmware v1.0.3 and newer	FOCTT2_FWUP_Mac v1.0.9 includes firmware v1.1.1.

## Supported OS Compatibility

<i>Application</i>	<i>Support</i>	<i>Known Limitations</i>
Mac OS X 10.9.5 and newer	Yes	We expect this software to work correctly on all versions of MacOS X 10.9.5 or newer. If you encounter an issue, please see "Troubleshooting: Support."

## Tested OS Compatibility

<i>Application</i>	<i>Support</i>	<i>Known Limitations</i>
Mac OS X Mavericks	v10.9.5	
macOS El Capitan	v10.11.5	
macOS High Sierra	v10.13.4	

## Released Production Files

### Product Upgrade

#### Image Information

Filename: FOCTT2\_FWUP\_Mac\_1\_0\_9.dmg  
 Filesize: 4424241 bytes  
 CRC32: 643E067E  
 MD5: c0df4e7faae3a982d14ad744f39115ce  
 SHA1: c4010588afbeaf7ed7be8a43995f4cccfb847796  
 SHA256: f6270d22caed6b92ec4af61722df79f6043c48558856ad50f91e86eb7fc9a545  
 SHA512:  
 0f95d1dba10997e0b9153b07c573fe98a13f9da2610110a7f1d76563668cdaa120543ee167be6  
 9360fc3602f43c607e57674d904513c157d1e045e297acd3be5  
 RIPEMD160: d27cc808a11866b019e17db726add453951e1e16

## New Features

### New Features added in version 1.0.9

<i>Issue ID</i>	<i>Title</i>
OC-332	The firmware loader provides firmware v1.2.1.

# Resolved Issues

## Issues resolved by version 1.0.9

<i>Issue ID</i>	<i>Title</i>
	N/A

# Outstanding Issues

## New Issues

The following reported problems have been found since the previous release and are still outstanding in this release.

<i>Issue ID</i>	<i>Title</i>	<i>Version</i>	<i>Status</i>
	N/A		

## Existing Issues

The following reported problems were found prior to the previous release and are still outstanding.

<i>Issue ID</i>	<i>Title</i>	<i>Version</i>	<i>Status</i>
OCBgz115	When updating a tool from 1.0.3 to 1.0.6, the word "Complete" did not propagate correctly.	BL2.03	Fixed in BL2.04

**OCBgz115** Sometimes the status reported by Bootloader v2.03 is not accurate when the firmware update has failed or when it has completed successfully.

*Workaround:* If other USB devices are attached to the computer, remove them. If no other USB devices are attached to the computer, then attach another USB device, or plug the OptiCam2 into a different USB port, or plug the OptiCam2 into a USB hub. Retry the firmware update procedure until the OptiCam2 LCD screen shows the updated firmware version at the top of the "... "Select Option" screen.

---

## Document History

Revision	Date	Reason for Change
1	Sep 29, 2022	Include firmware 1.2.1.